


FIG. 3








FIG. 5




FIG. 6




FIG. 7

PATTERN NAME	Α	В	С	
SOLDER TYPE PARAMETER	S1	S2	S3	
SQUEEGEE MOVEMENT SPEED	V1	V2	V3	
PRINTING PRESSURE	P1	P2	P3	
PLATE RELEASE PATTERN	1		III	
PLATE RELEASE SPEED	v1	v2	v3	

FIG. 8




FIG. 9




FIG. 10 (a)




FIG. 10 (b)




FIG. 11 (a)




FIG. 11 (b)






FIG. 12








FIG. 13 (b)




FIG. 13 (c)

